

Prazna kundtova cev

Frekvenca	Lpmax 1	Lpmin1	Lpmin2	Lpmin3	xmin1
125	81.5	51			680
250	83.5	52.5	54		346
500	79.3	52.5	53		175
1000	78	53	52.5	54	87
2000	79	/	55.5	55.5	123
4000	77.5	/	53	53.5	110

Vzorec v cevi

Frekvenca	Lpmax 1	Lpmin1	Lpmin2	Lpmin3	xmin1
125	77.5	52			695
250	78	56	56		346
500	81	65.5	65		175
1000	80.5	70	69.5		87
2000	82	/	76	75.5	119
4000	79.5	/	75.5	76	107

xmin2

1006

498

258

206

150

xmin2

1023

516

258

203

147